

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-34/24.

---


### Piper PA-34 (Seneca) Series Aeroplanes

### AD/PA-34/24      Engine Control Rod End Bearings - Inspection      11/2008 and Replacement

Requirement:      CANCELLED.

This AD is cancelled on 23 October 2008.

Background:      This AD specified inspection and replacement of engine control-rod end bearings. The inspection was not based on a Piper service document. USA AD 77-23-03 specified the same inspection. This AD and 77-23-03 required compliance within 25 hours time in service after November 1977 so the AD is no longer required.



Charles Lenarcic  
Delegate of the Civil Aviation Safety Authority

11 September 2008