

Piper PA-36 (Pawnee Brave) Series Aeroplanes

---

**AD/PA-36/17**

**Rudder Spar - Inspection**

**4/77**

Applicability: All models with S/Nos. 36-7360001 to 36-7760003.

Document: Piper SB No. 518.

Compliance: Within 100 hours time in service after 30 April 1977 and thereafter at intervals not exceeding 100 hours time in service until rudder is replaced.