

Piper PA-38 (Tomahawk) Series Aeroplanes

AD/PA-38/4 Amdt 1	Pilot's Control Wheel Installations - Inspection and Modification	9/87
------------------------------	--	-------------

Applicability: As detailed in Piper SB No. 609A.

Document: Piper SB No. 609A.

Compliance: Unless already accomplished, in accordance with SB No. 609, within 25 hours time in service after 31 October 1978.