
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-38/18.

Piper PA-38 (Tomahawk) Series Aeroplanes

AD/PA-38/18 Aileron Torque Tube Bearing - Inspection 13/2008

Requirement: CANCELLED.

This AD is cancelled on 18 December 2008.

Background: This unique Australian AD specified inspection of aileron torque tube bearings in accordance with Piper SB No. 709. Compliance was required within 100 hours time in service after September 1981. The AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

5 November 2008