

Piper PA-44 (Seminole) Series Aeroplanes

AD/PA-44/5 **Engine Priming System - Modification** **8/79**

Applicability: Model PA-44-180 with S/Nos. 44-7995001 to 44-7995190.

Document: 1. Piper SB No. 634; or
 2. FAA AD 79-12-11, Amendment 39-3490.

Compliance: Within 25 hours time in service after 29 June 1979.

Background: The engine fuel primer system of this aircraft is subject to cracking of lines and breakage of fittings and poses a fire hazard.