
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-44/10 Amdt 1.

Piper PA-44 (Seminole) Series Aeroplanes

**AD/PA-44/10
Amdt 1**

Engine Mount Frame Cracking

13/2008

Requirement: CANCELLED.

This AD is cancelled on 18 December 2008.

Background: This unique Australian AD specified periodic inspection of engine mounts until reinforcement by welding in accordance with Piper SB No. 719. Inspection was required at intervals not exceeding 100 hours time in service. Using an AD to mandate this inspection is no longer warranted.



David Villiers
Delegate of the Civil Aviation Safety Authority

5 November 2008