
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-46/13.

Piper PA-46 (Malibu) Series Aeroplanes

AD/PA-46/13

Flap Actuator Tube

4/2009

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD specified action on the flap actuator tube in accordance with Piper SB No. 862 within 100 hours time in service after July 1987 or the next scheduled maintenance release inspection after July 1987, whichever occurred later. The AD is no longer required.



David Punshon
Delegate of the Civil Aviation Safety Authority

3 February 2009