

Transavia PL 12 Series Aeroplanes

AD/PL 12/4

Stub Wing Structure - Inspection

12/68

Applicability: All models.

Requirement: Inspect the stub wing leading edge tube for cracking in the vicinity of landing gear attachment.

Compliance: Within 100 hours time in service after 14 February 1969 and thereafter at intervals not exceeding 100 hours time in service.