

Transavia PL 12 Series Aeroplanes

---

**AD/PL 12/5**

**Rudder Pedal Assemblies - Inspection**

**5/69**

Applicability: All models not modified to Transavia Dwg. 7-254 Issue C or later.

Requirement: Inspect the rudder pedal assemblies for cracking in all welded areas.

Compliance: Within 100 hours time in service after 4 July 1969 and thereafter at intervals not exceeding 100 hours time in service.