

Transavia PL 12 Series Aeroplanes

**AD/PL 12/14
Amdt 1**

Nose Landing Gear Pivot Pin and Bushes

2/89

Applicability: PL 12 and PL 12U.

Requirement: 1. Replace nose landing gear Pivot Pin P/N 6-24 Issue "C" and Bushes P/N 6-22 Issue "A" with Pin P/N 6-24 Issue "D" and Bushes P/N 6-22 Issue "B" or with Pin P/N 6-33 and Bushes P/N 6-34.

2. Inspect nose landing gear Pivot Pin P/N 6-24 Issue "D" or 6-33 for tooling or machine marks. Reject those pins with tooling or machine marks.

Note: Pin P/N 6-24 Issue "D" is same as Pin P/N 6-33 and Bush P/N 6-22 Issue "B" is same as Pin P/N 6-34.

Compliance: For Para. 1 - Unless already accomplished, within 25 hours time in service after 31 October 1973.

For Para. 2 - (i) For Installed Pins: Within 100 hours time in service after 31 October 1973.

(ii) For Spare Pins: Before installation.

Background: This Amendment deletes "All models" from the "Applicability" and reflects design and manufacturing improvements to later model aircraft.