

Percival Proctor Series Aeroplanes

**AD/PROCTOR/7
(Re-Issue)**

Wing Centre Section - Inspection

6/50

Applicability: All marks not modified in accordance with Proctor Mod. No. C1205.

Requirement: 1. Inspect the gap between the centre section nose and the outer plane and ensure that it is not large enough to allow the top pin to rotate and partially withdraw.

2. If the gap is found to be too large modify the flange of the joint pin safety bracket in accordance with Proctor Modification No. C1205; or

DCA/PROCTOR/7, or

A.N.O. 105.1.26.2.6.2.

Compliance: Forthwith.