

Robin Aviation Series Aeroplanes

AD/ROBIN/14

Fuel Tank Selector Valve

7/92 DM

Applicability: All ATL and ATL"S" Series Robin aircraft.

Requirement: Action in accordance with the technical requirements of DGAC AD 88-050(A) dated 30 March 1988.

Note: Robin SA Service Bulletin No 5 refers.

Compliance: By 22 May 1992. Thereafter, reinspect at intervals not exceeding 50 hours time in service.

Background: The manufacturer reports that due to an operational incident a repetitive inspection of the fuel selector valve is required.