

Robin Aviation Series Aeroplanes

AD/ROBIN/17

Safety Harness Link

7/92

Applicability: ATL, all types.

Requirement: Action in accordance with ROBIN SA SB No.6 Rev 1.

Note: DGAC AD 89-075(A) R1 refers.

Compliance: Unless already accomplished; Within 50 hours time in service after 25 June 1992.

Background: The DGAC requires modification action in order to prevent the nut of the quick-disconnect link to unscrew.