
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/ROCK-114/5.

Gulfstream (Rockwell) 114 Series Aeroplanes

AD/ROCK-114/5

**Throttle Control Cable - Inspection
and Modification**

9/2008

Requirement: CANCELLED.

This AD is cancelled on 28 August 2008.

Background: This unique Australian AD, raised in 1978 against Rockwell International Service Bulletin (SB) No. SB-114-2, required an inspection and/or modification to prevent possible throttle control cable failure.

Compliance was within 100 hours TIS after 30 June 1978.

As and all affected aircraft would have been inspected and/or modified by now, this AD is considered to be no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

17 July 2008