COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/ROCK-114/9.

Gulfstream (Rockwell) 114 Series Aeroplanes

AD/ROCK-114/9

Fuel Tank Access Door Sealant - Replacement

10/2008

Requirement: CANCELLED.

This AD is cancelled on 25 September 2008.

Background: This unique Australian AD, raised in 1980 against Rockwell International Service

> Bulletin (SB) No. SB-114-19, required replacement of fuel tank access door sealant due to long term exposure effects of aviation fuel, resulting in possible fuel screen

contamination.

Compliance was within 100 hours TIS after 31 December 1979.

As and all affected aircraft would be in compliance by now, this AD is considered to

be no longer required.

James Coyne

Delegate of the Civil Aviation Safety Authority

25 July 2008