
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/SM-205/26.

SIAI Marchetti S205 and S208 Series Aeroplanes

AD/SM-205/26 Engine Air Induction Valve - Replacement 7/2009

Requirement: CANCELLED.

This AD is cancelled on 2 July 2009.

Background: This Australian AD raised in 1977 against SIAI Marchetti Service Bulletin (SB) SB 205B45 required a modification to prevent fuel injector icing problems by installation of a redesigned engine induction valve assembly with manual control of alternative air source.

Compliance was: Within 25 Hours TIS after 30 April 1977.

This AD has been sufficiently promulgated for the affected aircraft to have been modified by now; therefore this AD is considered to be no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

18 May 2009