

SIAI Marchetti S205 and S208 Series Aeroplanes

---

**AD/SM-205/32 Engine Induction Valve Assembly P/No. 205-5-260- 5/82  
101 or P/No. 205-5-260-01 - Modification**

Applicability: All models S205/20F and S205/20R with S/Nos. referenced in SIAI Marchetti SB No. 205 B55 or with S/Nos. listed in subsequent issues of that SB.

Document: 1. SIAI Marchetti SB No. 205B55. or  
2. RAI AD 82-10/5205-47.

Compliance: Unless already accomplished, within 100 hours time in service after 31 May 1982.

Background: Breakage or loss of the MS 9048-006 pins securing the butterfly to the valve has been experienced overseas.