

SIAI Marchetti S205 and S208 Series Aeroplanes

AD/SM-205/34
Amdt 1

Wing Rear Spar - Inspection

3/84

Applicability: All models S205-18/F, S205-20F; S205-18/R, S205-20/R, S205-22/R, S208, S208A.

Requirement: SIAI-Marchetti S.B. No. 205B57.

Compliance: Unless already accomplished, before further flight and thereafter at intervals not exceeding 50 hours time in service.

Background:

- a. The manufacturer has received reports of cracking in the wing rear spar at the locations described above.
- b. This Directive has been amended to reflect the revised Aircraft Applicability and Requirement Document reissue.