COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/SWSA226/27.

Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes

AD/SWSA226/27

Wing Main Spar - Inspection for Manufacturing Defects

6/2009

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, raised in 1979 against Swearingen Service Bulletin (SB) SB 57-015,

required a Radiographic inspection of the wing main spar for double-drilled figure-of-

eight holes or other defects in the W.S.99 and W.S.81 areas. Compliance was

required within 300 hours TIS after 30 June 1979.

As all affected aircraft would have been inspected, and, if necessary, repaired long

ago, this AD is no longer required.

David Villiers

Delegate of the Civil Aviation Safety Authority

24 April 2009