

Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes

AD/SWSA226/64

Engine Power Lever

2/92

Applicability: Model Serial Numbers

SA226-T T201 through T275 and T277 through T291

SA226-T(B) T(B)276 and T(B)292 through T(B)417

SA226-AT AT001 through AT074

SA226-TC TC201 through TC419

SA227-TT TT421 through TT541

SA227-AT AT423 through AT695

SA227-AC AC406, AC415, AC416 and AC420 through AC777

SA227-BC BC762, BC764, BC766 and BC777

Requirement: Modify the power lever detent arms and cover assembly in accordance with Fairchild SB 226-76-008 or SB 227-76-002, as applicable.

Note: FAA AD 91-23-04 Amdt 39-8073 refers.

Compliance: Within 100 hours time in service after 3 February 1992.

Background: This Directive requires a one-time modification of the engine power lever flight idle detent arms and cover assembly. It has been reported that significant wear has caused improper operation of the engine power control levers on the affected aircraft.