

Aerospatiale (Socata) TB9 and TB10 (Tobago) Series Aeroplanes

AD/TB10/9

Stabilator Control Rod Ends

4/87 DM

Applicability: All models with S/Nos 1 to 709, except S/Nos 652, 653, 661, 664, 665, 672, 691, 701 to 706.

Requirement: Action in accordance with Socata S.B. No. 29.

Note: Bureau Veritas AD 87-003(A) refers.

Compliance: Within 25 hours time-in-service after 6 February 1987 and thereafter at each scheduled inspection for Maintenance Release issue until modified.

Background: The manufacturer reports instances of stabilator operating rod ends with excessive play due to loose rivets.