
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/TB10/13.

Aerospatiale (Socata) TB9 and TB10 (Tobago) Series Aeroplanes

AD/TB10/13 Aircraft Wiring/Support Bracket Clearance 7/2009

Requirement: CANCELLED.

This AD is cancelled on 2 July 2009.

Background: This unique Australian AD specified once-only inspection of aircraft wiring in the vicinity of the LH firewall door within 100 hours time in service after February 1990. The inspection was not based on a service document. The AD is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

18 May 2009