

Aerospatiale (Socata) TB9 and TB10 (Tobago) Series Aeroplanes

AD/TB10/19

Autopilot Master Switch

2/92

Applicability: All model TB10 aircraft series with serial numbers 275 through 1222 fitted with one of the following options:

668, G668, 669, G669, 670 or G670.

Requirement: Action in accordance with Aerospatiale SOCATA Service Bulletin No 60.

Note: DGAC AD 91-145A refers.

Compliance: Prior to the next Maintenance Release after 28 February 1992.

Background: To reduce the risk of a short circuit at the "A/P Master" switch.