

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

AD/TB20/2 Landing Gear Micro Switches - Adjustment 3/85

Applicability: All model TB20 with S/Nos up to and including 459.

Requirement: Adjust the undercarriage micro switches according to the requirements contained in Socata TB SB No 23.

Note: French AD 85-4(A) refers.

Compliance: Within 50 hours time in service after 31 March 1985.

Background: Compliance with this Directive will minimise the possibility of inadvertent undercarriage collapse.