

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

AD/TB20/3

**Elevator/Elevator Tab Control Attachment
Inspection and Modification**

4/85 TX

Applicability: All models TB20 with S/Nos up to and including 479.

Requirement: Socata TB SB No. 24 Modification No. 48.

Compliance: Operation 1: before further flight after 22 February 1985.

Operation 2: within 100 hours time in service after 22 February 1985.

Background: Socata warns of the risk of play in the tab rod/lever attachment.