

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

AD/TB20/6

Autopilot Pitch Servo Cable Guards

2/86 DM

Applicability: All model TB20 with KAP 150/KFC 150 autopilot to STC SA 1785CE-D.

Requirement: King SB KS 177/178-3 Note: FAA AD 85-25-02 also refers.

Compliance: Within 10 hours time in service after 16 January 1986.

Background: An installation problem has been identified which can result in jamming of primary pitch control. This condition has occurred in service.