

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

---

**AD/TB20/7**

**Stabilator Control Rod Ends**

**4/87 DM**

Applicability: All models with S/Nos 1 to 709, except S/Nos 652, 653, 661, 664, 665, 672, 691, 701 to 706.

Requirement: Action in accordance with Socata S.B. No. 29.

*Note: Bureau Veritas AD 87-003(A) refers.*

Compliance: Within 25 hours time-in-service after 6 February 1987 and thereafter at each scheduled inspection for Maintenance Release issue until modified.

Background: The manufacturer reports instances of stabilator operating rod ends with excessive play due to loose rivets.