

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

AD/TB20/17
Amdt 1

Front Seat Safety Belts

3/95

Applicability: All Model TB20 AND TB21 series aircraft.

Requirement: Action in accordance with SOCATA Mandatory Service Bulletin 10.044.25 Amendment 1.

Note: DGAC AD 89-097(A)R1 refers.

Compliance: Prior to 2 March 1996, and thereafter at intervals not to exceed 12 calendar months.

Background: Seat belt anchorage fittings are hidden by aircraft trim and therefore are not readily inspectable for corrosion.

Amendment 1 is issued to align this Directive with a revision of the Country of Origin AD which reduces the inspection interval.