

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

AD/TB20/23

Console Attachment

11/91

Applicability: Model TB20 and TB21 with serial numbers 1 through 1286.

Requirement: Action in accordance with the Technical Requirement of DGAC AD 91-160 (A).

Note: SOCATA TB aircraft SB 49 refers.

Compliance: Within 50 hours time in service after 31 October 1991, and thereafter at intervals not to exceed 200 hours time in service; until Kit No. 9172 is installed.

Background: Cracks have been reported on frame No. 0 at the nose gear mount lower attachments.