

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

---

**AD/TB20/33**                      **Upper Attachment of Front Seat Belts**                      **11/96 DM**

Applicability:    S/Nos. 1 to 1701, 1707 to 1750, 1758 to 1763, 1767 and 1769.

Requirement:    Action in accordance with Socata SB 10-103-25.

*Note: DGAC AD 96-143(A) refers.*

Compliance:    Within 50 hours time in service, or 30 days, after 14 August 1996 whichever occurs first.

Background:     This Directive is issued to ensure the integrity of the upper attachment of the front seat belts.