

Aerostar (Piper/Ted Smith) 600 and 700 Series Aeroplanes

AD/TSA-600/31

**Turbocharger Oil System Supply
Hose - Replacement**

7/83

- Applicability: All models of PA-60-601 Aerostar with S/Nos. 61-0342-112 through 61-0880-8162157 and prior airframe sequence numbers having retrofit option 106 (automatic wastegate controller) installed. PA-60-601P Aerostar with S/Nos. 61P-0157-001 through 61P-0860-8163455. PA-60-602P Aerostar with S/Nos. 62P-0750-8165001, 62P-0861-8165002 through 60-8365010.
- Document: Piper SB No. 761.
- Compliance: Within 100 hours time in service after 31st August 1983.
- Background: Reports have been received by the manufacturer of burned and chafed Turbocharger oil supply hoses. This condition will be alleviated by the fitting of higher temperature hoses and rerouting.