

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/4 Outboard Elevator and Tailplane Hinge - Inspection 3/63

Applicability: Victa Airtourer 100 and 115 with S/Nos. 1 to 14 not incorporating Mod. B27.

Requirement: Inspect the outboard elevator and tailplane hinge fittings P/N 0221012 and 0220009 for cracks, particularly in the region of the bend radius on the elevator hinge P/N 0221012.

Compliance: At intervals not exceeding 25 hours time in service, after 1 September 1971.