

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/5

**Control Column Torque Tube Bearing
Spigots - Modification**

3/63

Applicability: Victa Airtourer 100 and 115 with S/Nos. 1 to 16.

Document: Victa SB No. 6.

Compliance: Before 1 September 1971.