

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/16 Elevator Stops on Torque Shaft - Modification 5/64

Applicability: Victa Airtourer 100 and 115.

Document: 1. Victa SB No. 30; or
 2. Victa Mod. B87.

Compliance: Before 1 September 1971.