

Victa and A.E.S.L. Airtourer Series Aeroplanes

---

**AD/VAT/19A**

**Exhaust Muffler Baffle - Inspection**

**6/68**

Applicability: Airtourer 115.

Document: Victa Alert SB No. A.35.

Compliance: At intervals not exceeding 100 hours time in service, after 1 September 1971.