

Victa and A.E.S.L. Airtourer Series Aeroplanes

---

**AD/VAT/22C**

**Nose Leg Strut - Modification**

**5/66**

Applicability: Victa Airtourer 100 and 115 not incorporating Mod. B206.

Document: Victa SB No. 48, Issue 3.

Compliance: Before 500 hours total time in service.