

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/24

**Rear Fuselage - Sealing of Seams and
Rivets - Modification**

11/65

Applicability: Victa Airtourer 100 and 115 with S/Nos. 1 to 110.

Document: Victa SB No. 55.

Compliance: Within 100 hours time in service after 29 November 1965.