

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/25

Nose Wheel Steering - Inspection

11/65

Applicability: Victa Airtourer 100 and 115 prior to S/Nos. 108 not incorporating Mod. No. B209.

Document: Victa SB No. 49, Issue 2.

Compliance: At intervals not exceeding 100 hours time in service.