

Victa and A.E.S.L. Airtourer Series Aeroplanes

**AD/VAT/32
Amdt 1**

Nose Wheel Steering Arm - Inspection

8/68

Applicability: Airtourer 100 and 115.

Requirement: Inspect the riveted joint of four 5/32 inch rivets in the steering arm assembly P/N 62011/1 for looseness and evidence of rivet working.

Note: This inspection may be performed and certified by the pilot.

Compliance: At each daily or overnight inspection.