

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/35

Fuel Cell - Inspection

7/70

Applicability: All models fitted with P/No. DC3681 fuel cells.

Requirement: Inspect the fuel cell to ensure that the rubber support channels are adequately bonded to the upper surface of the cell.

Compliance: 1. For installed fuel cells - within 100 hours time in service after 31 July 1970.
2. For spar fuel cells - before installation in an aeroplane.