

Victa and A.E.S.L. Airtourer Series Aeroplanes

---

**AD/VAT/40                      Elevator Centre Rib Structure - Modification                      10/75**

Applicability:    All models.

Document:        Aerospace Airtourer SB No. 038.

Compliance:     Within 100 hours time in service after 31 October 1975.