

Cessna 340 Series Aeroplanes

**AD/CESSNA 340/7
Amdt 6**

Engine Exhaust System

3/87

Applicability: All Turbocharged models.

Requirement: 1. Inspect engine exhaust system in accordance with Cessna SIL No. ME75-17, including “Expanded inspection and maintenance instructions” as detailed in Cessna SIL No. ME79-32.

2. Inspect those items listed in Table 2 of Cessna SIL No. ME79-32.

3. Replace multi-segment “V” band exhaust clamps listed in Table 3 of Cessna SIL No. ME79-32.

Note: FAA AD 75-23-08 Amdt 39-5451 refers.

Compliance: 1. At intervals not exceeding 50 hours time in service.

2. At intervals not exceeding 100 hours time in service.

3. At intervals not exceeding 750 hours time in service.

Background: This Directive has been amended to include reference to the latest FAA AD amendment.