

Auxiliary Power Units

AD/APU/1 Turbine Blade Containment Ring - Installation NK

Applicability: Airesearch Model No
 GTCP85-98D with Serial No. prior to 28008.
 -98W with Serial No. prior to 30734.
 -99 with Serial No. prior to 14744.
 -115 with Serial No. prior to 18801.
 -115C with Serial No. prior to 35975.

Document: Airesearch SB No. 49-1790.

Compliance: Before installation in an aircraft following next reconditioning or hot end repair after
 30 November 1971.