

**AIRWORTHINESS DIRECTIVE**

---

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 003/12.

---

**Airbus Industrie A330 Series Aeroplanes**

**AD/A330/15  
Amdt 1**

**Flap Rotary Actuators**

**3/2012**

Requirement: CANCELLED.

This AD is cancelled on 13 February 2012.

Background: A State of Design airworthiness directive issued on or after 1 October 2009 is defined as an airworthiness directive per CASR Part 39.001A. The requirements of this airworthiness directive have been superseded by EASA AD 2012-0020 issued on 30 January 2012.