

Boeing 727 Series Aeroplanes

AD/B727/78
Amdt 1

**Engine Fuel Feed Forward Shroud Hose
Assemblies - Inspection and Modification**

5/83

Applicability: All models listed in Boeing SB No. 727-28-51 Rev. 2.

Document: 1. Boeing SB No. 727-28-51, Rev. 2; or
2. FAA AD 77-03-02, Amdt. 39-4572.

Compliance: As detailed in the requirement documents.

Background: This Directive is amended to include the latest revision status of FAA AD 77-03-02 which removes the need of repeat inspection after the installation of corrosion resistant braided hoses. Inspection and modification is required following the discovery by the manufacturer of braid corrosion in hoses constructed with carbon steel braid.