

Boeing 727 Series Aeroplanes

AD/B727/88
Amdt 2

Main Cargo Door Cam Support Fittings

7/84

Applicability: All 727-100 series aircraft listed in the requirement document.

Document: Boeing Alert Service Bulletin 727-52A124. Revision 6 including Addendum.

Note: FAA AD 80-08-10 also refers.

Compliance: As detailed in requirement document.

Background: Cracking of these fittings has been found in service and has been attributed to cabin pressurisation fatigue. Alert SB 727-52A124 has been revised to incorporate all pertinent inspection requirements into applicable sections of the Service Bulletin.