

Boeing 737 Series Aeroplanes

---

**AD/B737/27**                      **TE Flap Track Support Fitting Attach Bolts**                      **8/91**  
**Amdt 1**

Applicability:    Model 737-300 and -400 series as listed in Boeing ASB 737-57A1202 Revision 1.

Requirement:    Action in accordance with the Technical Requirements of FAA AD 91-09-17 Amdt 39-6984.

Compliance:    As specified in the Requirement Document with a revised effective date of 8 August 1991 for Australian registered aircraft.

Background:     Incorrect material bolts and nuts may have been used to attach the outboard flap inboard track support fitting.

Amendment 1 is prompted by information from the manufacturer which indicated that additional aircraft were not inspected for the proper nuts before they left the factory.