
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/B737/31.

Boeing 737 Series Aeroplanes

AD/B737/31

**Fuselage - Longitudinal Lap Joint
Lower Skin at Left and Right Stringer 14**

7/2006

Requirement: CANCELLED.

This AD is cancelled on 6 July 2006.

Background: This Airworthiness Directive is superseded by AD/B737/281.



David Villiers
Delegate of the Civil Aviation Safety Authority

23 May 2006