

Boeing 737 Series Aeroplanes

AD/B737/45
Amdt 1

Takeoff Configuration Warning System

12/90

Applicability: All model Boeing 737 series aircraft as listed in Boeing Service Bulletin 737-31-1033 Revision 1.

Requirement: Modify the logic which enables Takeoff Configuration Warning Systems (TOCWS) in accordance with Boeing Service Bulletin 737-31-1033 Revision 1 or later revision.

Compliance: Prior to 6 September 1992.

Background: Compliance with this AD is required in order to prevent takeoff configuration warning system nuisance warnings when taxi operations are conducted with the flaps intentionally retracted.

Amendment 1 to this AD is issued to clarify the applicability.