
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this airworthiness directive (AD) is revoked by CASA ADCX 019/15.

Boeing 737 Series Aeroplanes

**AD/B737/87
Amdt 2**

Fuselage Lap Joints, Lower Skins

24/2015

Requirement: CANCELLED.

This AD is cancelled on 17 December 2015.

Background: The requirements of this AD have been superseded by FAA AD 2015-21-06 issued on 11 October 2015.